
File No.:20206-27
"Transmission Line Parasitic Element
Discontinuity Cancellation"
d: October 3, 2001 Frank G. Mikalauska

Filed: October 3, 2001 Frank G. Mikalauskas Serial No.: 09/970,550

1/5








FIG. 2




.50

2/5



3/5



4/5

RSL traces-110 um width Buddy traces-35 um width 35 um space

FIG S

` '

5/5




FIG. 6